

~~line 34, change "scabs" to read --drosses--.~~

Page 2

~~lines 3, 25 and 26, change "scabbing" to read
--dross-forming--; and~~

~~line 12, change "scab-reducing" to read --dross-reducing--.~~

Cont

A3

Page 3

~~line 24, change "scab" to read --dross--; and
lines 25, 31 and 34, change "scabbing" to read
--dross-forming--.~~

Page 4

~~Table 2, column 4, change "Scabbing" to read
--Dross-Forming--; and
last line, change "scabbed" to read --drossed--.~~

IN THE CLAIMS

~~Cancel claims 1-6, all the claims in the case, and
substitute the following claims therefor.~~

~~7. Process which comprises reducing the susceptibility to
dross-forming of an aluminum alloy melt with a content of at
least 2.5 wt.% magnesium, including adding to the melt from 0.02
to 0.15 wt.% vanadium and less than 60 ppm beryllium.~~